



Die Maintenance Handbook

David A. Smith



Society of
Manufacturing
Engineers
www.sme.org

Table of Contents

Preface	xiii
Contributors	xvii
1 An Overview of Basic Die Operations	1
Cutting, Punching, and Perforating	1
Bending and Forming	2
Bending and Straightening	3
Stretching	4
Drawing	6
Squeezing or Coining Operations	6
Analytical Tools	8
2 Troubleshooting Punching and Cutting Operations	11
Understanding the Sequence of Operations	11
Effect of Die Clearance	15
Cutting Forces	21
3 Designing Large EDM Die Sections for Repairability	27
Application of EDM Technology	27
Throwaway versus Repairable Die Sections	28
Die Section Location and Retention	29
Punch and Die-steel Design	30
Conclusion	32
4 Die-shaving Operations	33
Purpose	33
Punch-to-die Clearance	34
Size of Shave Punch versus Part Hole Size	34
Multiple Shaving Operations	34
Application of the Hollow-ground Concept	36

5 Solving Punch Head Breakage Problems	39
Punch Head Breakage	39
Safety of Personnel	45
Function of the Punch Backing Plate	46
Ironworker- and Bulldozer-style Punches	47
6 The Cost of Punch and Die Maintenance	49
Record Causal Factors	49
The Real Cost of Die Damage	51
The Value of Good Workmanship	51
7 Good Maintenance Practice	53
Good Grinding Practice	53
Stress-relieving Cutting Tools	63
Shimming Die Components	65
Ball-lock Punches and Die Buttons	69
8 Compound Dies	73
Compound Blank and Piercing Dies	73
9 Pressure Pad and Stripper Selection	79
Positive or Tunnel Strippers	79
Pressure Systems for Pads and Strippers	81
Elastomer Strippers	86
Stripping Forces	87
10 Anti-slug Pulling Methods	89
Resolving Slug-pulling Problems	89
Overview of Methods	97
11 Cutting Force and Snap-through Reduction	101
Types of Punch Shear	101
Punching Thick Carbon Steel	102
Importance of Timing	104
Press Reverse-load Capacity	105
Die Timing Improvement	106
Providing Angular Shear on the Die	108
Summary	110

12 Bending of Metals	111
Bend Allowances	113
Press-brake Operations	115
Wipe-bending Die Operations	117
Rotary-action Die-bending Operations	119
Control of Bend Angle by Adjusting Pad Pressure	122
13 Forming Flanges and Hems	129
Flanging Operations	129
Flange Types	129
Minimum Bend Radii	132
Stock Thickness Variation	133
Hemming Operations	136
Pressures	137
14 Drawing and Stretching of Metals	141
Deep Drawing of a Cylindrical Cup	141
Stretch Forming	148
Bending and Straightening	149
Drawing and Bending	150
15 Stamping Analysis Techniques	157
Computerized Analysis Techniques	158
Circle Grid Analysis	159
16 Die Maintenance Documentation and Tracking	167
Die Maintenance Team	167
A Systematic Die Maintenance System	168
The Request for Maintenance Form	175
Case Study	176
Continuous Improvement	180
17 Effective Die Maintenance Program Strategy	183
Understanding the Die Maintenance Facility	183
Addressing Production-scheduling Problems	184
Planning Die Maintenance	185
Tracking the Cost of Maintenance and Downtime	186

Continuous Improvement	186
Spare Parts Inventory	190
Calculating Costs	193
Pareto Charting	200
Dealing with an Outside Vendor	203
Used Dies	204
Good Engineering Practice	205
18 Metallic Springs as Die-pressure Devices	211
Types of Metal Springs	211
Materials Used to Make Metal Springs	215
Selecting Springs	216
Considerations When Repairing Dies	220
Analysis of Spring Failures	222
Winding Springs In-house	225
Conclusion	225
19 Gas and Hydraulic Die-pressure Systems	227
Pneumatic Cylinders	227
Nitrogen Die-pressure Systems	231
Nitrogen Manifold Systems	235
Self-contained Nitrogen Cylinders	237
Hydraulic Die-pressure Systems	243
20 Press Selection and Maintenance	247
Press Terminology	247
Types of Presses	250
Overload Protection	259
Mechanical Press Drives	260
Speed Reduction and Torque Capacity	268
Mechanical versus Hydraulic Presses	268
Upgrading Existing Presses	275
Die Cushions	275
Centering the Load in the Press	278
21 Troubleshooting Large Panel Stamping Dies	283
Die Bolting	283
Nitrogen Pressure Systems	286

A Systematic Approach to Die Tryout	286
Draw Beads	291
Double-action Press Operations	295
Dirt Problems	295
Forming Ribs and Embossments	297
Knockout Bars	299
22 Waveform Signature Analysis	301
Stress-strain Curves	301
Case Study: Webster Industries	302
Diagnosing Hydraulic Overload Problems	307
Press-tonnage Curves	311
Detecting Waveform Changes	315
Die- and Press-protection Systems	317
Conclusion	320
23 Repairing Damaged Die Steels and Castings	323
Making the Repair Decision	323
Mechanical Repair Techniques	325
Electrical Welding Repairs	333
24 Die Materials and Treatments	339
Characteristics of Tool and Die Steels	340
Choosing Tool Steels	340
Heat Treatment of Die Steels	353
Tool Steel Production Methods	358
Die Surface Coatings and Treatments	360
Wrought Low-carbon Steels and Cast Irons	363
Nonferrous and Nonmetallic Die Materials	365
Appendix A: Generic Die Standards	371
Design-and-build Process	371
Production and Safety	372
Quotes	373
Completion	373
Cancellations and Damages	374
Designing Strong Die Sections	375
Screws, Dowels, and Keys	377

Die Shoes, Subplates, and Parallels	379
Die Springs	380
Strip Starting Stops	382
Commercial Perishable Details	383
Pads and Strippers	384
General Tool Steel Details	385
Guide Pin, Bushing, Heel Block, Keeper, and Wear Plates	386
Scrap Discharge	387
Stock Sensors	388
General Good Practice	388
OSHA and Additional Die Identification	389

Appendix B: Case Study—	
Phoenix Specialty Manufacturing Company	391
Order Entry	391
Machine Shop Capabilities	392
Plant Culture	394
Spare Parts Storage	394
Ergonomics	395
Aluminum Die Sets	396
Bench Die Build Up	398
Quick Die Change Capabilities	399
An Eye to the Future	400
Conclusion	400
Index	403